

TRANSIT INFORMATION

ST HELENS BARWAY

NOTICE TO MARINERS M147-07 ENTRANCE TO GEORGES BAY

This Notice supersedes Notice M89-07. Mariners seeking access to the Port of St Helens are cautioned that they must cross an ocean barway prior to entering Georges Bay. Conditions at the St Helens entrance are currently poor, with shallow depths reported at the barway.

Sand shoals at the barway are moving constantly. Mariners are cautioned to seek up to date local knowledge and assess the barway carefully before making a crossing.

Further to Notice M07-07, the current depth along the track adjacent to Pelican Point inside Georges Bay is approximately 1.5 metres.

10 Feb
2007



05 March
2007



10 March
2007



31 March
2007



10 April
2007



5 Dec 2007



8 Jan 2008

